Energy performance certificate (EPC) recommendation report

Siop Uned 2 33 Station Road AMMANFORD SA18 2DB

Report number 0275-8215-0425-6376-7834

Valid until 27 March 2035

Energy rating and EPC

This property's energy rating is E.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/5523-2776-2738-3100-8563).

Recommendations

Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	High
Add time control to heating system.	Low
Add optimum start/stop to the heating system.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Add local temperature control to the heating system.	Medium
Add weather compensation controls to heating system.	Low
Add local time control to heating system.	Low
Changes that may pay for themselves within 3 to 7 years	
Recommendation	Potential impact on carbon emissions
	Potential impact on carbon emissions Medium
Recommendation	·
Recommendation Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Recommendation Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Recommendation Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium Medium Medium
Recommendation Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Some glazing is poorly insulated. Replace/improve glazing and/or frames. Consider installing an air source heat pump.	Medium Medium Medium
Recommendation Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Some glazing is poorly insulated. Replace/improve glazing and/or frames. Consider installing an air source heat pump. Changes that may pay for themselves in over 7 years	Medium Medium Medium High

Property and report details

Report issued on

28 March 2025

Total useful floor area	27 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	CLG, iSBEM, v6.1.e, SBEM, v6.1.e.0

Assessor's details

Assessor's name	Robin gerard
Telephone	07796 424191
Email	dyfedenergy@gmail.com
Employer's name	Dyfed Energy Assessment
Employer's address	Pontyates, Llanelli
Assessor ID	QUID200713
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Quidos Limited

Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at mhclg.digital-services@communities.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.

Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5) Service performance (/service-performance)

OGL

All content is available under the <u>Open Government Licence v3.0</u> (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/), except where otherwise stated



ht (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framewor