# Energy performance certificate (EPC) recommendation report

The Former Railway Club Station Approach Abercynon MOUNTAIN ASH CF45 4SB Report number 0448-7316-6155-9256-8274

> Valid until 10 May 2032

#### Energy rating and EPC

This property's current energy rating is C.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/4776-2290-4788-0292-8278).

#### Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

### Changes that pay for themselves within 3 years

Recommendation	Potential impact
Add time control to heating system.	Medium
Add optimum start/stop to the heating system.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Add local temperature control to the heating system.	Medium
Add weather compensation controls to heating system.	Medium

https://find-energy-certificate.service.gov.uk/energy-certificate/0448-7316-6155-9256-8274

Recommendation	Potential impact
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Add local time control to heating system.	Medium
Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Changes that pay for themselves in more than 7 years	
Recommendation	Potential impact
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Consider installing building mounted wind turbine(s).	Low
Consider installing solar water heating.	Low
Consider installing PV.	Low
Additional recommendations	
Recommendation	Potential impact
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low

#### **Report issued on**

11 May 2022

# Total useful floor area

182 square metres

#### **Building environment**

Heating and Natural Ventilation

# **Calculation tool**

Elmhurst Energy Systems Ltd, SBEM Online, v4.03, SBEM, v5.6.b.0

# Assessor's name

**Christopher Dixon** 

#### Telephone

07885637443

#### Email

cm\_dixon@hotmail.co.uk

#### **Employer's name**

Pen-y-Bont EPC & SAP

#### **Employer's address**

22 Tyn y Bettws Close, Bettws, Bridgend, CF32 8YF

#### Assessor ID

EES/022268

#### Assessor's declaration

The assessor is not related to the owner of the property.

#### Accreditation scheme

Elmhurst Energy Systems Ltd

#### Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <u>dluhc.digital-services@levellingup.gov.uk</u> or call our helpdesk on 020 3829 0748.

There are no related reports for this property.