Energy performance certificate (EPC)

Black Park Chapel Trust Ltd Maes Y Parc Chirk WREXHAM LL14 5BB Energy rating

Valid until: 20

20 March 2032

Certificate number:

4424-6674-9279-8047-8856

Property type

D1 Non-residential Institutions - Community/Day Centre

Total floor area

364 square metres


Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

You can read guidance for landlords on the regulations and exemptions (https://www.gov.uk/government/publications/non-domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance).

Energy efficiency rating for this property

This property's current energy rating is E.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

How this property compares to others

Properties similar to this one could have ratings:

If newly built

22 | A

If typical of the existing stock

73 | C

Breakdown of this property's energy performance

Main heating fuel

Dual Fuel Appliances (Mineral + Wood)

Building environment

Heating and Natural Ventilation

Building emission rate (kgCO2/m2 per year)

103.67

Primary energy use (kWh/m2 per year)

544

What is primary energy use?

Recommendation report

Guidance on improving the energy performance of this property can be found in the recommendation report (/energy-certificate/3882-8505-2873-5029-4255).

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

Assessor contact details

Assessor's name

Carl Hughes

Telephone

01978 345 250

Email

carl@hdsarchitectural.co.uk

Accreditation scheme contact details

Accreditation scheme

Stroma Certification Ltd

Assessor ID



Telephone

0330 124 9660

Email

certification@stroma.com

Assessment details

Employer

<insert Employer/Trading Name>

Employer address

<insert Employer/Trading Address>

Assessor's declaration

The assessor is not related to the owner of the property.

Date of assessment

5 August 2021

Date of certificate

21 March 2022

Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at dluhc.digital-services@levellingup.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.

Energy performance certificate (EPC) recommendation report

Black Park Chapel Trust Ltd Maes Y Parc Chirk WREXHAM LL14 5BB

Report number 3882-8505-2873-5029-4255

Valid until 20 March 2032

Energy rating and EPC

This property's current energy rating is E.

For more information on the property's energy performance, <u>see the EPC for this property (/energy-certificate/4424-6674-9279-8047-8856)</u>.

Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

Changes that pay for themselves within 3 years

Potential impact
Low
Medium
Medium
Potential impact
Medium
Medium
Medium

Recommendation	Potential impact
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Changes that pay for themselves in more than 7 years	
Recommendation	Potential impact
Install more efficient water heater.	High
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Consider installing building mounted wind turbine(s).	Low
Consider replacing HWS with point of use system.	Medium
Consider installing PV.	Low
Property and report details	
Report issued on	
21 March 2022	
Total useful floor area	
364 square metres	
Building environment	
Heating and Natural Ventilation	
Calculation tool	
CLG, iSBEM, v5.6.b, SBEM, v5.6.b.0	
Assessor's details	
Assessor's name	
Carl Hughes	
Telephone	
01978 345 250	

Email

carl@hdsarchitectural.co.uk

Employer's name

<insert Employer/Trading Name>

Employer's address

<insert Employer/Trading Address>

Assessor ID

STRO007308

Assessor's declaration

The assessor is not related to the owner of the property.

Accreditation scheme

Stroma Certification Ltd

Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at dluhc.digital-services@levellingup.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.